

NEW OILING GUIDE

■ ABOUT NEW OILING GUIDE

Can change the ceramic yarn contact part.

■ Reduces cost by about 50%.

- Cost less 40% when replacing the yarn contact part only.
- No cost to buy the metal holder.
- Cost of gluing is zero.

■ Replace time is shorter

- Because no need to glue the metal holder.

■ Other

- Waste material (metal holders and adhesives) is reduced.
- The problems caused by adhesive mistakes are eliminated.
(Oil leaks or defective yarn...)
- Easy to replace ceramic parts.
- We offer trial price when customer consider using the original product.



■ ASSEMBLE MANUAL



■ HOW TO CHOOSE

Body Guide part	 F010024	 F202040-A	 F202040-B	Specifications
F308080	F308081	F308082	F308888	Channel width : 1.3~0.6 , Oil hole : 0.5×1.0
F302222	F308009	F308010	F308011	Channel width : 1.2 , Oil hole : 0.6×2.0
F306020	F106035	F304021	F304022	Channel width : 1.0 , Oil hole : φ 1.0
F306040	F306042	F306043	F306044	Channel width : 1.2 , Oil hole : φ 1.2
F303054	F302052	F302053	F302054	Channel width : 1.0~0.5 , Oil hole : φ 0.7
F306077	F110040	F306065	F306066	Channel width : 1.2~0.6 , Oil hole : 0.6×2.1
F309077	F110041	F309065	F309066	Channel width : 1.0~0.6 , Oil hole : φ 1.0
F309090	F110006	F110030	F301190	Channel width : 2.3~1.0 , Oil hole : 0.6×1.5
F301050	F110007	F205013	F301150	Channel width : 2.1~1.0 , Oil hole : 0.6×1.5
F408080	F408081	F408082	F408888	Channel width : 1.3~0.6 , Oil hole : 0.5×1.0
F406020	F406035	F404021	F404022	Channel width : 1.0 , Oil hole : φ 1.0

※ Depending on the yarn standard choose a suitable oiling guide. Please feel free to contact us.

※ Utility Model Patent in China 201721171115.2

※ This leaflet is confidential and the property of YUASA YARN GUIDE ENGINEERING CO.,LTD.



湯浅糸道工業株式会社

〒468-0066 名古屋市中区元八事1丁目47番地

TEL (052) 831-7282 FAX (052) 834-5105 E-mail: Head-office@yuasa-yarnguide.co.jp